

Oil Field Environmental Incident Summary

Incident: 20160531151631

Date/Time of Notice: 05/31/2016 15:16

Responsible Party: MUREX PETROLEUM CORPORATION

Well Operator: MUREX PETROLEUM CORPORATION

Well Name: LALIM 27-1

Field Name: TIOGA

Well File #: 7858

Date Incident: 5/30/2016

Time Incident: 07:40

Facility ID Number:

County: WILLIAMS

Twp: 158

Rng: 95

Sec: 27

Qtr: SW SW

Location Description:

Submitted By: William Jansky

Received By:

Contact Person: Shannon Holter
363 N. Sam Houston Pkwy. E.
Suite 200
HOUSTON, TX 77060

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	14	Barrels	13	Barrels		

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

None

Action Taken or Planned:

The valve was shut to stop the release. A vacuum truck was called to recover spilled crude oil. Remediation to start as soon as weather permits

Wastes Disposal Location: Production tank. Bioremediation of remaining area.

Agencies Involved:

Updates

Date: 5/31/2016 ***Status:*** Reviewed - Assigned to Other Agency ***Author:*** Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release remained on location according to the report. NDIC retains oversight.